


SHANK TAPER INSPECTION INSTRUMENTS



gauge master (optional)

- Check the taper of BT shank
- Supplied with dial indicators



check:

d₁: large taper diameter

d₂: small taper diameter

L: straightness of the taper

a: relationship of the flange to the taper

SPECIFICATION

Code	4773-30	4773-40	4773-50
Taper	BT30	BT40	BT50
Repeatability	1μm	1μm	1μm

OPTIONAL ACCESSORY

Gauge master for 4773-30	4773-S1
Gauge master for 4773-40	4773-S2
Gauge master for 4773-50	4773-S3