
TAPER GAGES

measure diameter of hole



when measuring diameter of holes, correction on reading is needed due to the thickness of taper gage. for example, when reading A is 14.96mm, diameter ØD is 15mm.

measure slot width




- Measure opening, slot width, hole diameter, etc.
- Diameter correction table on the back (only for 4833-1, 4833-2)
- Made of stainless steel

| Code | Range | Graduation | Accuracy | L | W |
|--------|----------|------------|----------|-------|--------|
| 4833-1 | 0.8-15mm | 0.1mm | ±0.05mm | 146mm | 17mm |
| 4833-2 | 15-30mm | 0.1mm | ±0.05mm | 159mm | 30.4mm |
| 4833-3 | 30-45mm | 0.1mm | ±0.05mm | 166mm | 45.4mm |
| 4833-4 | 45-60mm | 0.1mm | ±0.05mm | 170mm | 60.5mm |





back



4833-2