


NO NEED TO SET
ZERO BEFORE USE

MINI LEVELS




4959-84B

Unit: mm



4959-84A/84B



20

- To check the level of equipment
- No need to set zero before use




4959-100A

Unit: mm



4959-100A/100B



20

Code	Length	Graduation
4959-84A	84mm	0.3mm/m (0.0171°)
4959-84B	84mm	0.45mm/m (0.0257°)
4959-100A	100mm	0.1mm/m (0.0057°)
4959-100B	100mm	0.3mm/m (0.0171°)