
## DATA OUTPUT CABLES (KEYBOARD FORMAT)





7302-21

- Recognized as HID keyboard device by computer, no need to install drivers and softwares
   Data can be transmitted to Excel, Word, txt and other files (press transmit button, which is recognized by the computer as keyboard input data and press enter key, such as 12.34 \( \nabla \)
- For any softwares which can receive keyboard signal
- Optional accessory: foot switch (code: 7304-2), hub (code: 7324-HUB4, 7324-HUB7),

| extension cables (code: 7325-ADD5, 7325-ADD10) |  |                                       |  |  |  |
|--|--|---------------------------------------|--|--|--|
| Code   | Description  | Plug                                  | Connecting with measuring tool   | Transmit data  |  |
| 7302-21  | cable for<br>digital calipers<br>(length 3m)         |                                       | button   | <ul> <li>Press the button on the plug of cable, can also press the button of the transmit box, or press the foot switch</li> <li>Data is transmitted once, the signal light of the transmit box flashes once</li> </ul>  |  |
| 7302-22  | cable for large<br>digital calipers<br>(length 2.5m) | 111                                   |  | <ul> <li>Press the button of the transmit box, or press the foot switch</li> <li>Data is transmitted once, the signal light of the transmit box flashes once</li> </ul>  |  |
| 7302-30  | cable for digital<br>micrometers<br>(length 2.5m)    |                                       | signal light "data" button back  for 3102, 3128, 3565 series digital micrometers | <ul> <li>Press the "data" button of digital micrometer, can also press the button of the box, or press the foot switch</li> <li>Data is transmitted once, the signal light of the transmit box flashes once, at the same time, the signal light on the digital micrometer flashes once</li> </ul>          |  |
| 7302-31  | cable for digital<br>micrometers<br>(length 2.5m)    | e e e e e e e e e e e e e e e e e e e | signal light "data" button   | <ul> <li>Press the "data" button of digital micrometer, can also press the button of the transmit box, or press the foot switch</li> <li>Data is transmitted once, the signal light of the transmit box flashes once, at the same time, the signal light on the digital micrometer flashes once</li> </ul> |  |

| Code      | Description  | Plug | Connecting with measuring tool                 | Transmit data  |
|-----------|--|------|--|--|
| 7302-50M  | cable for<br>digital gauges<br>(length 2.5m)                       | -111 |  | <ul> <li>Press the button of the transmit box, or press the foot switch</li> <li>Data is transmitted once, the signal light of the transmit box flashes once</li> </ul>  |
| 7302-40M  | cable for digital<br>indicators<br>(length 2.5m)                   |      | for 2108, 2138, 2139 series digital indicators | <ul> <li>Press the "DATA" button of digital indicator, can also press the button of the transmit box, or press the foot switch</li> <li>Data is transmitted once, the signal light of the transmit box flashes once, at the same time, the signal light on digital indicator flashes once</li> <li>Note: long press button to zero the digital indicators</li> </ul> |
|           |  |      | for other digital indicators                   | <ul> <li>Press the button of the transmit box, or press the foot switch</li> <li>Data is transmitted once, the signal light of the transmit box flashes once</li> </ul> Note: long press button to zero the digital indicators   |
|           |  |      |  | digital indicators   |
| 7302-60   | cable for<br>high precision<br>digital indicators<br>(length 2.5m) |      | "DATA" button                                  | <ul> <li>Press the "DATA" button of high precision digital indicator, can also press the button of the transmit box, or press the foot switch</li> <li>Data is transmitted once, the signal light of the transmit box flashes once</li> </ul>  |
| 7302-3350 | cable for digital<br>micrometers<br>(length 2.5m)                  | -111 | "DATA" button                                  | <ul> <li>Press the "DATA" button of digital micrometer, can also press the button of the transmit box, or press the foot switch</li> <li>Data is transmitted once, the signal light of the transmit box flashes once</li> </ul>  |
| 7302-1151 | cable for digital<br>height gauges<br>(length 2.5m)                | -111 | [5 885] = = = = = = = = = = = = = = = = = = =  | <ul> <li>Press the button of the transmit box, or press the foot switch</li> <li>Data is transmitted once, the signal light of the transmit box flashes once</li> </ul>  |
| 7302-SPC7 | cable for digital<br>height gauges<br>(length 2.5m)                |      |  | <ul> <li>Press the button of the transmit box,<br/>or press the foot switch</li> <li>Data is transmitted once, the signal light<br/>of the transmit box flashes once</li> </ul>  |