


## WEIGHING SCALES (HIGH PRECISION)

- LCD display, with backlight
- Zero-setting, subtracting tare value
- Overload alarm
- Automatic power off



8001-30



**ATTENTION:  
NO DATA OUTPUT**

Part No.	8001-6	8001-15	8001-30
Capacity	6kg	15kg	30kg
Minimum capacity	4g	10g	20g
Readout	0.2g	0.5g	1g
Resolution	30000d		
Operating temperature	14~104°F		
Power supply	rechargeable battery (6V/3.2Ah) power adapter (12V/500mA)		
Dimensions of pan	10.354×8.031"		